

Stats 2/7/08 Davila

Commercial Pallet Co
725 Independent Road
Oakland, CA 94621
(510) 632 8519
(510) 631 2082 –FAX

6 EE's

General violations:

2340.1 Electrical wiring damaged on horizontal pallet saw.- General - \$100
6151(e)(1) Fire extinguisher not checked.-General- \$100
3664(a)(1) No forklift training - General - \$100
3457(c)(3)(G)(3) Bathroom no soap.-General -\$100
3364(b) no door on bathroom.-General-\$100
3203(a) no IIPP- General -\$100
3366(b) water did not work - General - \$100
3366(d) no soap - General -\$100

Richmond Pallet Company
146 So 1st Street
Richmond CA 94801

6 EE's

Serious violations

4307(c) Skill saw pinned back.	\$2,000
4075(a) Chain and sprocket drive unguarded	\$2,000

General violations

6151(e)(1) Fire extinguisher not checked.	\$100
5097 (a) No hearing conservation program.	\$100
2500.8(a) Electrical cord run through wall.	\$100
3273(a) Inadequate workspace	\$100
2340.1 Ground removed from electrical wiring on saw.	\$100
3664(a)(1) No forklift training	\$100
3203(a) no IIPP	\$100
3364(d) no toilet paper	\$100
3366 no handwashing water	\$100
3363(a) no drinking water provided	\$100

Duenas Pallets
575 Brookside Drive
Richmond, CA 94801
(510) 237 0817

7 ee'S

Serious :

4307(c) Skill saw pinned back.-Serious - \$2000

General:

3364(b) toilet dirty-\$100

2340.1 Electrical wiring damaged on horizontal pallet saw.-\$100

3366(d) no soap or handwashing water-\$100

3364(d) no toilet paper-\$100

3664(a)(1) No forklift training-\$100

3203(a) no IIPP-\$100

3241(c) pallets stacked dangerously -\$100

3361(c) Forklift no horn - \$100