Stats for 2/6/08 Davila

All State Pallet 710 73rd Ave. Oakland 96621 (510) 562-8164

5 employees

Serious

4300(a) Table saw unguarded -\$2000 4307(a) Skill saw not properly guarded-\$2000

Generals

3203(a) no IIPP - \$1002340.1 wiring damaged on table saw- \$1003664(a)(1) No forklift training-\$1003382(a) no eye protection-\$1006151(c) fire extinguisher inaccessible-\$1003660(a) no load limit sign-\$1003457(c)(3)(G)(3) No soap-\$1003664(b) handwashing sink cluttered-\$100

Lopez Pallet Company 616 Derby Ave. Oakland CA 94601 (510) 586-6090

5 employees

Serious: 4307(a) skill saw not guarded.-\$2000

General

2340.1 Electrical wiring damaged on horizontal pallet saw.-\$100 3203(a) no IIPP-\$100 3664(a)(1) No forklift training-\$100 3382(a) no eye protection-\$100 3364(d) no toilet paper-\$100 3366 no handwashing water \$100 3364(b) toilet dirty-\$100 2340.1 wiring unsafe-\$100

GMC Pallet 4300 San Leandro Oakland CA. 94621 4 employees

Serious

2340.1 240v Spider box electrical sitting in wet locations and in poor condition.\$2000

4650(e) propane tank on the back of the forklift was unsecured.-\$2000 3364(a) no bathroom facilities \$2000

General:

3273(a) Inadequate workspace \$100 3382(a) no eye protection \$100 2340.1 wiring damaged on skill saw \$100 3203(a) no IIPP \$100 3664(a)(1) No forklift training \$100 3400(c) No first aid kit \$100

Claro Pallets 822 53rd Avenue Oakland CA 94601 (510) 228 5494

6 ee's

Serious: 3070(a) Unguarded belt and pulley drive \$2000

General

2340.1 wiring damaged on skill saw \$100 3272(c) ailesways partially blocked \$100 6151(e)(1) Fire extinguisher not checked.\$100 3664(a)(1) No forklift training \$100 3364(b) no door on bathroom.\$100 3366 no handwashing water \$100 3203(a)No IIPP \$100 3400(c) No first aid kit \$100 3220 No warning sign of automatic start on compressor \$100